осоро с.	Work for Property Loc					lorth 58th	<u> </u>			
	Property is: Single Far	nily 🔽	L	Ouplex		Other \square				-
Date:	9/10/2015	_								
ake no respo	minimum requirement to meet honsibility for problems discovered by private lenders, insurance co	after the ir	nspe	ction dat	te, or for or	nissions throu	igh error or	oversight.	•	•
Exterior	Condition Report									
Location Site	Required Work Landscaping	n/a] Y	es 🗸	Note/Co Self Help	omments			\$	Cost 500.00
	Steps/Handrails	n/a ✓] Y	es 🗌					\$	
	Service walks	n/a ☑] Y	es 🗌					\$	
	Fencing	n/a ☑	Y	es 🗌					\$	
	Parking	n/a	Y	es 🗸					\$	1,800.00
	Retaining walls	n/a ✓	Y	es 🗌					\$	
	Other	n/a] Y	es 🗆					\$	
	Other	n/a	Y	es 🗌					\$	
Garage	Singles: repair	n/a ☑] Y	es 🗌					\$	
	Shingles: Roof over existing	n/a ☑	Y	es 🗌					\$	
	Shingles:Tear off & re-roof	n/a	Y	es 🗸					\$	1,500.00
	Gutters/downspouts	n/a ✓	Y	es 🗌					\$	
	Flashing	n/a ✓] Y	es 🗌					\$	
	Eaves	n/a ☑] Y	es 🗌					\$	
	Siding	n/a ☑	Υ	es 🗌					\$	
	Doors	n/a ✓	Υ	es 🗌					\$	
	Windows	n/a ☑	Y	es 🗌					\$	
	Slab	n/a ✓	Υ	es 🗌					\$	
	Paint	n/a ✓	Υ	es 🗌					\$	
	Electrical	n/a ✓	Υ	es 🗌					\$	
_	Other	n/a	Y	es 🗌					\$	
Porches	Roof	n/a ☑] Y	es 🗌					\$	
	Deck-upper	n/a ☑] Y	es 🗌					\$	
	Decklower	n/a ✓	Υ	es 🗌					\$	
	Steps/handrails	n/a ☑	Y	es 🗌					\$	
	Ceiling	n/a ☑	Y	es 🗌					\$	
	Guardrails	n/a ☑	Y	es 🗌					\$	
	Structural	n/a ✓	Υ	es 🗌					\$	
	Paint	n/a	Y	es 🗸					\$	70.00

n/a 🗌 Yes 🗌

\$

Other

House

Chimney	n/a ☐ Yes ☑	\$ 500.00
Shingles: repair	n/a ☑ Yes 🗌	\$
Shingles: Roof over existing	n/a ☑ Yes □	\$
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$ 8,750.00
Gutters/downspouts	n/a ✓ Yes 🗌	\$
Flashing	n/a ✓ Yes 🗌	\$
Eaves	n/a ☑ Yes 🗌	\$
Siding	n/a ☑ Yes 🗌	\$
Storm Doors	n/a ☑ Yes 🗌	\$
Prime ("main") Doors	n/a ✓ Yes 🗌	\$
Storm Windows	n/a ☑ Yes 🗌	\$
Prime ("main") Windows	n/a ☑ Yes 🗌	\$
Paint	n/a ☑ Yes □	\$
Foundation	n/a ☑ Yes □	\$
Electrical	n/a ☑ Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$

Exterior: Estimated Cost:* \$ 13,120.00

 $[\]mbox{^*}\mbox{average}$ contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report Unit: Entire unit (single family)	7		Lower unit of duplex		
Mechanical Heating	Upper unit of duplex Required Work			Other		
ricating	Repair/replace boiler	n/a ✓	Yes 🗌		\$	
	Repair radiation	n/a ✓	Yes 🗌		\$	
	Repair/replace furnace	n/a ✓	Yes 🗌		\$	
	Repair ductwork	n/a ✓	Yes 🗌		\$	
	Replace thermostat	n/a ✓	Yes 🗌		\$	
	Repair/replace grilles	n/a ✓	Yes 🗌		\$	
Electrical	Tune boiler/furn. insp ht exchange	g n/a	Yes 🗸		\$	350.00
Electrical	Repair/replace receptacles	n/a ✓	Yes 🗌		\$	
	Repair/replace switches	n/a ✓	Yes 🗌		\$	
	Repair/replace fixtures	n/a ✓	Yes 🗌		\$	
	Install outlets and circuits	n/a ✓	Yes 🗌		\$	
	Install outlets and circuits	n/a ✓	Yes 🗌		\$	
	Install outlets and circuits	n/a ✓	Yes 🗌		\$	
	Install outlets and circuits	n/a ✓	Yes 🗌		\$	
	Upgrade service	n/a ✓	Yes 🗌		\$	
	Other	n/a	Yes 🗌		\$	
	Other	n/a	Yes 🗌		\$	
Plumbing	Repair/replace kitchen sink	n/a 🗌	Yes 🗸		\$	519.00
	Repair/replace kitchen sink fauce	∈n/a 🗌	Yes ✓		 \$	345.00
	Repair/replace tub	n/a ✓	Yes 🗌		\$	
	Repair/replace tub faucet	n/a ✓	Yes 🗌		 \$	
	Repair/replace toilet	n/a ✓	Yes 🗌		 \$	
	Repair/replace lavatory	n/a ✓	Yes 🗌		 \$	
	Repair/replace lavatory faucet	n/a ✓	Yes 🗌		\$	
	Repair/replace wash tub	n/a ✓	Yes 🗌		 \$	
	Repair/replace wash tub faucet	n/a ✓	Yes 🗌		 \$	
	Unclog piping:	n/a ✓	Yes 🗌		 \$	
	Repair drain/waste/vent piping	n/a ✓	Yes 🗌		 \$	
	Repair water piping	n/a ✓	Yes 🗌		 \$	
	Repair/replace water heater	n/a ✓	Yes 🗌		 \$	
	Other	n/a	Yes 🗸	Permit Required	\$	85.00

n/a 🗌 Yes 🗌

Other

Windows												
	Replace broken glass	n/a	V	Yes			\$					
	Repair or replace sash	n/a	V	Yes			\$					
Doors	Danair ar rankaa daara	- /-	7	V			¢					
	Repair or replace doors	n/a		Yes	<u> Ц</u>		\$					
M-11-10-11	Repair or repl. locks/latches	n/a	✓	Yes		Self Help	\$					
Walls/Ceiling	gs Repair or repl. @ defective	n/a	V	Yes			\$					
Paint												
	Repair or repl. @ defective	n/a	V	Yes			\$					
Fire Safety												
•	Install smoke/CO alarm:bsmt.	n/a		Yes	V	Self Help	\$	60.00				
	Install smoke/CO alarm: 1st flr.	n/a		Yes	V	Self Help	\$	60.00				
	Install smoke/CO alarm: 2nd flr.	n/a	V	Yes		Self Help	\$					
Handrails												
04-1	Repair/replace defective	n/a	✓	Yes		Self Help	\$					
Stairs	Repair defective	n/a	V	Yes			\$					
Floors												
Other	Repair defective	n/a	J	Yes			\$					
		n/a		Yes			\$					
		n/a		Yes			\$					
		n/a		Yes			\$					
		n/a		Yes			\$					
						Interior: Estimated Cost:	\$	1,419.00				
						Total Exterior and Interior Cost:*	\$	14,539.00				
						*average contracted cost. Actual costs may vary. Self help will reduce the amount.						

Inspected by Eric Yanke

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Date: 9/10/2015

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.